

**Continental** 



May 5, 1999  
PS-99-40


Mr. Andre Covington  
Ultraseal International, Inc.  
1100 North Wilcox Ave.  
Los Angeles, CA 90038

Dear Mr. Andre Covington:

Enclosed is a Continental General Tire Limited Warranty and Adjustment Policy booklet. Please note under Section 4A. (What is Not Covered by the Adjustment Policy...), "*Tire failure resulting from intentional alteration, such as adding a white inlay on a blackwall or sealant materials.*" In other words, the added sealant material must have caused or lead to the tire failure before it voids Continental General Tire's Limited Warranty and Adjustment Policy.

If additional information is required or you have any questions, you may contact me directly by calling (704) 583-8895 or fax (704) 583-8673 or e-mail [rforsyth@generaltire.com](mailto:rforsyth@generaltire.com).

R.J. Forsyth



National Manager,  
Product Service/Consumer Relations

Enclosure

cc: K. Dumitru